


Debris Removal from the Upper Part of Unit 3 Reactor Building at Fukushima Daiichi Nuclear Power Station

< Reference >


April 22, 2013

Tokyo Electric Power Company


On April 22, 2013, the protection (first phase) has been installed on the spent fuel pool. The protection for the skimmer surge tank hatch cover (found on April 18, 2013) has also been installed. To prepare for the second phase of protection installation on the spent fuel pool, the steel beam truss debris, etc. which interfere with the work will be removed.



Simulated image of debris removal from the upper part of the operation floor



Simulated image of the protection installed on the spent fuel pool (first phase)



Simulated image of the protection to be installed on the spent fuel pool (second phase)



Debris Removal from the Upper Part of Unit 3 Reactor Building at Fukushima Daiichi Nuclear Power Station

< Reference >
April 22, 2013
Tokyo Electric Power Company




Photo taken on November 12, 2011

Before the debris in the surrounding area of the spent fuel pool was removed




Photo taken on March 20, 2013

Before the protection was installed on the spent fuel pool (first phase)



Photo taken on April 22, 2013

Protection installed on the spent fuel pool (first phase)